



Location : Block 1 Balcony corridors
Defect : Defective cantilever beams propped



Location : Cantilever Beam at 4/F of Block 1
Defect : Cantilever beam propped



Location : Cantilever Beam at 2/F of Block 1
Defect : Seriously spalled



Location : Cantilever Beam at 2/F of Block 1
Defect : Seriously spalled



Location : Cantilever Beam at 2/F of Block 1
Defect : Seriously spalled



Location : Cantilever Beam at 2/F of Block 3
Defect : Seriously spalled



Location : Cantilever Beam at 4/F of Block 5
Defect : Seriously spalled



Location : 4/F Column in Link Block
Defect : Cracks



Location : 3/F Column & Beam in Link Block
Defect : Vertical cracks




Location : 2/F Columns at Unit 208 & 209
Defect : Vertical cracks



Location : 1/F Cantilever Beam at Unit 28 & 29
Defect : Longitudinal cracks



Location : 1/F Beam at Link Block
Defect : Longitudinal cracks



Location : 1/F Beam at Link Block
Defect : Longitudinal cracks



Location : 3/F Slab at Link Block
Defect : Dampness at Ceiling



Location : 3/F Slab at Link Block
Defect : Dampness at Ceiling



Location : Block 2 - corridor at 4/F
Problem : Water seepage from toilet



Location : Block 2 - corridor at 4/F
Action : Water seepage rectified



Location : Block 1 - 5/F edge beam
Defect : Spalled concrete



Location : Block 2 - 6/F edge beam
Defect : Spalled concrete



Location : Block 1 - parapet at 5/F
Defect: Concrete spalled



Location : Block 1 - parapet at 5/F
Action : Hazard removed and repaired



Location : Block 2 - Slab at corridor at 5/F
Action: Recasting defective slab



Location : Block 2 - Ceiling at corridor at 4/F
Action : Spalling repair



Location : Block 2 – External wall
Defect : Structural elements in bad condition



Location: Wall at 6/F
Defect : Broken edge, seriously spalled



Location : Wall at 5/F
Defect : Broken edge, seriously spalled



Location : Wall at 6/F
Defect : Seriously spalled



Location : Wall at 3/F
Defect : Seriously spalled



Location : Wall at 2/F
Defect : Seriously spalled



Location : Wall at 1/F
Defect : Seriously spalled



Location : Block 1/link block edge columns
Defect : Seriously spalled



Location : Block 1/link block – 4/F column
Defect : Cracked



Location : Block 1/link block – 4/F column
Defect : Seriously spalled



Location : Block 1/link block - 2/F column
Defect : Seriously spalled



Location : Block 1/link block - 1/F column
Defect : Cracked



Location : Block 1/link block - 1/F column
Defect : Seriously spalled



Location : Block 1/link block - G/F column
Defect : Cracked
