

咸水樓拉力橫樑
鋼筋漲爆石屎



The image shows a corner of a room with significant structural damage. The ceiling is cracked and crumbling, with a red and white marker placed on it for scale. The wall on the left has a large horizontal section missing, revealing dark, rusted steel reinforcement bars (rebar) protruding from the concrete. The wall on the right is also cracked and peeling. A white pipe with a yellow electrical box is visible on the right wall. In the bottom right corner, there is a white container with a blue hose attached to it.

樓宇結構鋼筋漲爆石屎

橫樑鋼筋截斷石屎脫落





鋼筋銹蝕後剩下的模型



鋼筋漲爆石屎及瓷磚



鋼筋漲爆石屎情況嚴重



下
跌
屎
石
爆
漲
筋
鋼
樓
騎
人
路
傷
壓
險



險被騎樓石屎跌下
壓傷的途人



超過八成業主期望將物業集體出售增值後換樓