

## **Labour Department (Headquarters)**

勞工處(總處)

來函編號: CB2/PL/MP

檔案編號: (9a) in LD OD/1-55/79

電話號碼 : 2852 4070 傳真號碼 : 2544 3271

10 October 2017

Ms Betty MA
Clerk to the Panel on Manpower
Legislative Council
Legislative Council Complex
1 Legislative Council Road
Central
Hong Kong

Dear Ms Ma,

## Occupational Safety Condition of the Hong Kong-Zhuhai-Macao Bridge ("HZMB") Projects

I refer to the letter from the Secretariat of the Panel on Manpower dated 11 May 2017, enclosing a letter of 10 May 2017 from the then-legislator Ms LAU Siu-lai addressed to the Chairman of the Panel. The Administration is requested to provide further information concerning the occupational safety of the HZMB projects. The Labour Department ("LD") sets out its reply as follows.

With regard to disclosure of the names of the principal contractors and sub-contractors involved in the prosecution cases as listed in Annex II of CB(2)1357/16-17(05) where the legal proceedings have been completed, LD has considered further advice from the Department of Justice ("DoJ"). In light of the advice and with reference to the Code on Access to Information ("the Code"), the names of defendants and relevant information of the cases heard and convicted in the past two years are set out in Annex.

As regards the request for disclosure of the names of the duty holders in relation to the written warnings/Improvement Notices and Suspension Notices issued as mentioned in Annex I of CB(2)1357/16-17(05), LD is of the view that it is not appropriate to disclose such information upon seeking further advice from DoJ and making reference to the Code.

Yours sincerely,

(WU Wai-hung)

for Commissioner for Labour

Annex

## Conviction Records regarding the Hong Kong – Zhuhai – Macao Bridge Local Projects in the past two years

	Defendants	Project	Offence	Conviction Date
1	Tai Yau Woo	Tuen Mun - Chek Lap	Contravention of regulation 38B(1A) of the	8 Oct 2015
	Engineering Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to prevent person from falling from	
			a place of 2 m high or more	
2	Gammon Construction	Tuen Mun - Chek Lap	Contravention of regulation 52A(2) of the	8 Oct 2015
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	
3	Lam Geotechnics	Tuen Mun - Chek Lap	Contravention of regulation 44(1)(c) of the	15 Feb 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to guard dangerous part of machine	
4	Gammon Construction	Tuen Mun - Chek Lap	Contravention of regulation 44(1)(c) of the	15 Feb 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to guard dangerous part of machine	
5	VSL Hong Kong	Hong Kong Link	Contravention of sections 6A(2)(a) and	8 Jun 2016
	Limited	Road	13(1) of the Factories and Industrial	
			Ordinance: Guilty of the like offence of	
			another proprietor (sub-contractor) failing to	
			provide safe plant or safe system of work	

	NOT II. IZ	TT IV T '.1	(A(O)()) - 1	0 T 0016
6	VSL Hong Kong	Hong Kong Link	Contravention of sections 6A(2)(c) and	8 Jun 2016
	Limited	Road	13(1) of the Factories and Industrial	
			Ordinance: Guilty of the like offence of	
			another proprietor (sub-contractor) failing to	
			provide necessary information, instruction,	
			training and supervision	
7	China Harbour	Hong Kong Link	Contravention of sections of 6A(2)(a) and	8 Jun 2016
	Engineering Company	Road	13(1) of the Factories and Industrial	
	Limited		Ordinance: Guilty of the like offence of	
			another proprietor (sub-contractor) failing to	
			provide safe plant or safe system of work	
8	China Harbour	Hong Kong Link	Contravention of sections 6A(2)(c) and	8 Jun 2016
	Engineering Company	Road	13(1) of the Factories and Industrial	
	Limited		Ordinance: Guilty of the like offence of	
			another proprietor (sub-contractor) failing to	
			provide necessary information, instruction,	
			training and supervision	
9	Dragages Hong Kong	Hong Kong Link	Contravention of sections 6A(2)(a) and	8 Jun 2016
	Limited	Road	13(1) of the Factories and Industrial	
			Ordinance: Guilty of the like offence of	
			another proprietor (sub-contractor) failing to	
			provide safe plant or safe system of work	
10	Dragages Hong Kong	Hong Kong Link	Contravention of sections 6A(2)(c) and	8 Jun 2016
	Limited	Road	13(1) of the Factories and Industrial	
			Ordinance: Guilty of the like offence of	
			another proprietor (sub-contractor) failing to	
			provide necessary information, instruction,	
			training and supervision	
		<u> </u>	1	

11	Cally Engineering Limited	Hong Kong Link Road	Contravention of sections 6A(2)(a) of the Factories and Industrial Ordinance: Failure to provide safe plant or safe system of work	8 Jun 2016
12	Cally Engineering Limited	Hong Kong Link Road	Contravention of sections 6A(2)(c) of the Factories and Industrial Ordinance: Failure to provide necessary information, instruction, training and supervision	8 Jun 2016
13	Chung Wo Civil Engineering Limited	Hong Kong Link Road	Contravention of regulation 38B(1A) of the Construction Site (Safety) Regulations: Failure to prevent person from falling from a place of 2 m high or more	25 Aug 2016
14	Chung Wo Civil Engineering Limited	Hong Kong Link Road	Contravention of regulation 38AA(2) of the Construction Site (Safety) Regulations: Failure to provide adequate and safe means of access and egress	25 Aug 2016
15	Ming Shing Construction Engineering Company Limited	Hong Kong Link Road	Contravention of regulation 38B(1A) of the Construction Site (Safety) Regulations: Failure to prevent person from falling from a place of 2 m high or more	25 Aug 2016
16	China State Construction Engineering (Hong Kong) Limited	Hong Kong Link Road	Contravention of regulation 38A(2) of the Construction Site (Safety) Regulations: Failure to provide adequate and safe means of access and egress	25 Aug 2016
17	Fortress Development Limited	Hong Kong Link Road	Contravention of regulation 52A(2) of the Construction Site (Safety) Regulations: Failure to provide guard rails to prevent from falling into water	3 Oct 2016

18	VSL Hong Kong	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	
19	China Harbour	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to provide guard rails to prevent	
	,		from falling into water	
20	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	-
			from falling into water	
21	Fortress Development	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	
22	VSL Hong Kong	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	
23	China Harbour	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to provide guard rails to prevent	
			from falling into water	
24	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	

25	Hoi Cheung Engineering Company Limited	Hong Kong Link Road	Contravention of regulation 38AA(2) of the Construction Site (Safety) Regulations: Failure to provide adequate and safe means of access and egress	3 Oct 2016
26	Hoi Cheung Engineering Company Limited	Hong Kong Link Road	Contravention of regulation 38B(1A) of the Construction Site (Safety) Regulations: Failure to prevent person from falling from a place of 2 m high or more	3 Oct 2016
27	Hoi Cheung Engineering Company Limited	Hong Kong Link Road	Contravention of regulation 43(b) of the Construction Site (Safety) Regulations: Failure to ensure workers wearing eye protectors	3 Oct 2016
28	VSL Hong Kong Limited	Hong Kong Link Road	Contravention of regulation 38A(2) of the Construction Site (Safety) Regulations: Failure to provide adequate and safe means of access and egress	3 Oct 2016
29	VSL Hong Kong Limited	Hong Kong Link Road	Contravention of regulation 38B(1) of the Construction Site (Safety) Regulations: Failure to prevent person from falling from a place of 2 m high or more	3 Oct 2016
30	VSL Hong Kong Limited	Hong Kong Link Road	Contravention of regulation 43(b) of the Construction Site (Safety) Regulations: Failure to ensure workers wearing eye protectors	3 Oct 2016
31	China Harbour Engineering Company Limited	Hong Kong Link Road	Contravention of regulation 38A(2) of the Construction Site (Safety) Regulations: Failure to provide adequate and safe means of access and egress	3 Oct 2016

32	China Harbour	Hong Kong Link	Contravention of regulation 38B(1) of the	3 Oct 2016
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to prevent person from falling from	
	·		a place of 2 m high or more	
33	China Harbour	Hong Kong Link	Contravention of regulation 43(b) of the	3 Oct 2016
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to ensure workers wearing eye	
			protectors	
34	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 38A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
35	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 38B(1) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to prevent person from falling from	
			a place of 2 m high or more	
36	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 43(b) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to ensure workers wearing eye	
			protectors	
37	Hoi Cheung Engineering	Hong Kong Link	Contravention of regulation 38B(1A) of the	3 Oct 2016
	Company Limited	Road	Construction Site (Safety) Regulations:	
			Failure to prevent person from falling from	
			a place of 2 m high or more	
38	Hoi Cheung Engineering	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Company Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	

39	Hoi Cheung Engineering	Hong Kong Link	Contravention of regulation 38AA(2) of the	3 Oct 2016
39		Road		3 Oct 2010
	Company Limited	Roau	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
	TIOT IT TO	TT T T' 1	of access and egress	0.00016
40	VSL Hong Kong	Hong Kong Link	Contravention of regulation 38B(1) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to prevent person from falling from	
			a place of 2 m high or more	
41	VSL Hong Kong	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
		· ·	Failure to provide guard rails to prevent	
			from falling into water	
42	VSL Hong Kong	Hong Kong Link	Contravention of regulation 38A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
43	China Harbour	Hong Kong Link	Contravention of regulation 38B(1) of the	3 Oct 2016
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to prevent person from falling from	
			a place of 2 m high or more	
44	China Harbour	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to provide guard rails to prevent	
			from falling into water	
45	China Harbour	Hong Kong Link	Contravention of regulation 38A(2) of the	3 Oct 2016
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to provide adequate and safe means	
			of access and egress	
	<u> </u>			

46	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 38B(1) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to prevent person from falling from	
			a place of 2 m high or more	
47	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 52A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	·
			Failure to provide guard rails to prevent	
			from falling into water	
48	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 38A(2) of the	3 Oct 2016
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
49	Dragages Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 38A(2) of the	18 Nov 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
50	Dragages Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 38A(2) of the	18 Nov 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
51	Dragages Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 43(b) of the	18 Nov 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to ensure workers wearing eye	
			protectors	
52	China Harbour	Tuen Mun - Chek Lap	Contravention of regulation 38A(2) of the	18 Nov 2016
	Engineering Company	Kok Link	Construction Site (Safety) Regulations:	
	Limited		Failure to provide adequate and safe means	
			of access and egress	

53	China Harbour	Tuen Mun - Chek Lap	Contravention of regulation 38A(2) of the	18 Nov 2016
	Engineering Company	Kok Link	Construction Site (Safety) Regulations:	
	Limited		Failure to provide adequate and safe means	
		b .	of access and egress	
54	China Harbour	Tuen Mun - Chek Lap	Contravention of regulation 48(1)(b) of the	18 Nov 2016
	Engineering Company	Kok Link	Construction Site (Safety) Regulations:	
	Limited		Failure to ensure workers wearing safety	
			helmets	
55	VSL Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 38A(2) of the	18 Nov 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
56	VSL Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 38A(2) of the	18 Nov 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
57	VSL Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 48(1)(b) of the	18 Nov 2016
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to ensure workers wearing safety	
			helmets	
58	Hoi Cheung Engineering	Tuen Mun - Chek Lap	Contravention of regulation 7(b) of the	18 Nov 2016
	Company Limited	Kok Link	Factories and Industrial Undertakings	
			(Protection of Eyes) Regulations: Failure to	
			ensure workers wearing eye protectors	1033
59	Hoi Cheung Engineering	Tuen Mun - Chek Lap	Contravention of regulation 38AA(2) of the	18 Nov 2016
	Company Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	

60	Hoi Cheung Engineering	Tuen Mun - Chek Lap	Contravention of regulation 38AA(2) of the	18 Nov 2016
	Company Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide adequate and safe means	
			of access and egress	
61	Hoi Cheung Engineering	Tuen Mun - Chek Lap	Contravention of regulation 48(1A)(b) of	18 Nov 2016
	Company Limited	Kok Link	the Construction Site (Safety) Regulations:	
			Failure to ensure workers wearing safety	
			helmets	
62	VSL Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 52A(2) of the	8 Jun 2017
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	
63	China Harbour	Tuen Mun - Chek Lap	Contravention of regulation 52A(2) of the	8 Jun 2017
	Engineering Company	Kok Link	Construction Site (Safety) Regulations:	
	Limited		Failure to provide guard rails to prevent	
			from falling into water	
64	Dragages Hong Kong	Tuen Mun - Chek Lap	Contravention of regulation 52A(2) of the	8 Jun 2017
	Limited	Kok Link	Construction Site (Safety) Regulations:	
			Failure to provide guard rails to prevent	
			from falling into water	
65	Dragages Hong Kong	Hong Kong Link	Contravention of regulation 38B(1) of the	10 Aug 2017
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to prevent person from falling from	
			a place of 2 m high or more	
66	China Harbour	Hong Kong Link	Contravention of regulation 38B(1) of the	10 Aug 2017
	Engineering Company	Road	Construction Site (Safety) Regulations:	
	Limited		Failure to prevent person from falling from	
			a place of 2 m high or more	

67	VSL Hong Kong	Hong Kong Link	Contravention of regulation 38B(1) of the	10 Aug 2017
	Limited	Road	Construction Site (Safety) Regulations:	
			Failure to prevent person from falling from	
			a place of 2 m high or more	