

政府總部
香港下亞厘畢道



GOVERNMENT SECRETARIAT

LOWER ALBERT ROAD
HONG KONG

Tel. No.: 2810 3948
Fax No.: 2868 9159

本函檔號 OUR REF: SF(3) in SEC 9/1/100 (08)
來函檔號 YOUR REF: CB2/PL/SE

3 April 2009

Clerk to the Panel
Legislative Council Panel on Security
Legislative Council Building
8 Jackson Road
Central
Hong Kong
(Attn: Miss Josephine SO)

Dear Miss SO,

**Replacement of Four Fire Appliances of the
Fire Services Department**

At the meeting of the LegCo Panel on Security on 3 March 2009, Members made an enquiry about the number of fire appliances of the Fire Services Department (FSD) that were not equipped with power-assisted steering system. According to the information provided by the FSD, the Department only has two fire appliances that were not equipped with power-assisted steering system.

Yours sincerely,

(Miss YEN PUN)
for Secretary for Security

c.c. Director of Fire Services (Attn: Mr LI Leung-ming) Fax : 2739 8775