Panel on Environmental Affairs

<u>List of follow-up actions</u> (position as at 16 June 2015)

Subject	Date of meeting	Follow-up action required	Administration's response
Use of liquefied petroleum gas ("LPG") vehicles in Hong Kong		In view of the vehicle repair workshop explosion which happened in Wong Tai Sin on 26 April 2015, the Administration to provide an information paper on the use of LPG vehicles in Hong Kong, including details on the repair and maintenance of LPG vehicles, the statutory requirements and safety standards for an LPG vehicle workshop and a LPG filling station, the conduct of regular inspection of LPG vehicles and facilities, and the safety handling of LPG cylinders and other types of dangerous goods, as well as the berthing of vessels carrying dangerous goods in the vicinity of residential areas.	Response awaited

Council Business Division 1 Legislative Council Secretariat 16 June 2015