

# *Volume I*

## TABLE OF CONTENTS

### Part I – Main Report

Chapter	Contents	Page
<b>1</b>	<b>Introduction</b>	<b>8 ~17</b>
	A. Background	
	B. The Report	
<b>2</b>	<b>The Select Committee</b>	<b>18~22</b>
	A. Appointment of the Select Committee and its terms of reference	
	B. Membership of the Select Committee	
	C. Scope of inquiry	
	D. Collection of documents	
	E. Procedures for conducting the inquiry	
	F. Appointment of consultants	
	G. Schedule of meetings, visit, public hearings and witnesses	

<b>Chapter</b>	<b>Contents</b>	<b>Page</b>
<b>3</b>	<b>Key bodies, persons and dates</b>	<b>23~32</b>
	A. Key bodies and persons	
	B. Key dates	
<b>4</b>	<b>Finding of Facts I</b>	<b>33~101</b>
	A. Choice of 6 July 1998 as the opening date of the new airport	
	B. Flight Information Display System	
	C. Hong Kong Air Cargo Terminals Limited	
<b>5</b>	<b>Finding of Facts II</b>	<b>102~161</b>
	A. Building Works and Installation of Systems	
	B. Building Services	
	C. Baggage Handling System	
	D. Ramp Handling	
	E. Telephones	
	F. Public Address System	
	G. Airbridges	

<b>Chapter</b>	<b>Contents</b>	<b>Page</b>
	H. Signage	
	I. Training and Trials	
	J. Contingency Planning for and Crisis Management on Airport Opening Day	
<b>6</b>	<b>Finding of Facts III</b>	<b>162~179</b>
	A. Security	
	B. Noise under the flight paths	
	C. Overall economic loss in Hong Kong	
<b>7</b>	<b>Responsibilities</b>	<b>180~237</b>
<b>8</b>	<b>Lessons to be learned</b>	<b>238~248</b>
	<b>Acknowledgement</b>	<b>249~250</b>
	<b>Signatures of the Chairman, Deputy Chairman and members of the Select Committee</b>	<b>251</b>
	<b>Abbreviations</b>	<b>252</b>

## **Appendices**

**253**

- Appendix 1 List of documents obtained from the 18 relevant bodies and consultants from August 1998 to January 1999
- Appendix 2 Legislative Council resolution passed under section 15 of the Legislative Council (Powers and Privileges) Ordinance, Cap. 382
- Appendix 3 Consultancy report on “FIDS and FIDS-Related Problems Surrounding the Commencement of Operations at the Chek Lap Kok Airport” by the consultancy team of the University of Hong Kong academics, Part I – The Main Report, 12 November 1998
- Appendix 4 Summary Reports dated 20 November 1998 to the Legislative Council by IATA’s Consultants, Mr BOURKE and Captain JONASSON
- The Result of the Review of the Documentation on Flight Path Designs
  - The Result of the Review of the Documentation on Environmental Issues
- Appendix 5 “LegCo – Reply to Questions” dated 1 December 1998 from Mr BOURKE and Captain JONASSON

- Appendix 6 E-mail message dated 2 December 1998 at 2:09 am from Captain JONASSON
- Appendix 7 E-mail message dated 2 December 1998 at 10:52 pm from Captain JONASSON
- Appendix 8 Summary Report to Legislative Council by Mr BOURKE and Captain JONASSON on “Meeting on 17 December 1998 with the Hong Kong Civil Aviation Department and Environmental Protection Department concerning the Report by the LegCo Consultants on Documentation on Flight Path Designs and Noise Abatement Measures”
- Appendix 9 Letter dated 9 December 1998 from the Director of Civil Aviation (DCA) to Clerk to the Select Committee
- DCA’s response to the Summary Reports by IATA’s consultants (Attachment I)
  - DCA’s response to the conclusions and suggestions made by IATA’s consultants (Attachment II)
- Appendix 10 The Select Committee’s schedule of meetings, visit, public hearings and witnesses
- Appendix 11 The problem logs of the Flight Information Display System on 6 July 1998

Report of the Legislative Council Select Committee to inquire into the circumstances  
leading to the problems surrounding the commencement of the operation of  
the new Hong Kong International Airport at Chek Lap Kok  
since 6 July 1998 and related issues

---

*Volume I - Table of contents*

*Page 6*

---

**Part II – Minutes of Proceedings**

**254**