For discussion on 5 December 2016

Legislative Council Panel on Housing

Updates on Issues Arising from the "Excess Lead in Drinking Water in Public Rental Housing Estates" Incident

Purpose

Since the start of the "excess lead in drinking water in public rental housing (PRH) estates" incident, we have been providing the Legislative Council (LegCo) and the Hong Kong Housing Authority (HA) with updates on the major developments of various issues. This paper briefs Members on the latest developments in respect of the following areas –

- (a) progress of rectification works in the 11 affected PRH developments with excess lead in drinking water;
- (b) measures taken to enhance HA's quality assurance mechanism;
- (c) actions against contractors; and
- (d) water sampling test results for PRH estates.

Rectification Works in Affected PRH Estates

Rectification Works in the Common Areas of the 11 Affected PRH Estates

- 2. As reported to LegCo House Committee in July 2016, HA has asked the four contractors to replace non-compliant pipes in the 11 affected PRH developments in order to rectify the problem of excess lead in water. Rectification works in the common areas started in March 2016 and progress so far is generally satisfactory. On the whole, the contractors have completed more than half of the works in the common areas.
- 3. HA has asked the contractors to minimise the inconvenience to tenants as far as practicable, maintain close communication with tenants and address their issues or concerns. HA has also monitored the progress of works through regular meetings with the contractors. So far, we have not received major complaints or adverse feedback from tenants regarding rectification works in the

common areas except for some incidents of water leakage/pipe burst, which were partly caused by poor workmanship in using compression joints¹ and miscommunication among workers. In response to these incidents, contractors have carried out emergency repairs swiftly and handled claims from affected tenants. To prevent the recurrence of similar incidents, HA has asked the contractors to improve their installation method for compression jointing, enhance training for workers and tighten up procedures to avoid miscommunication.

- 4. The incidents above show that there is a higher risk of leakage/burst if the water pipes are connected by compression jointing rather than soldering. Therefore, the contractors have explored the feasibility of adopting alternative soldering methods. Subject to implementation of precautionary safety measures, the contractors may consider adopting soldering during rectification works as appropriate, particularly for the pipework inside flats and at external walls, special areas at which compression jointing is difficult and locations with a higher risk of leakage.
- 5. After replacement of water pipes in the common areas, water sampling tests will be conducted for the new pipes for various parameters, including lead, to ensure compliance with the Water Authority (WA)'s requirements.

Trial for Works Inside Flats

- 6. As reported earlier, the contractors will replace the non-compliant water pipes inside domestic units after the rectification works in the common areas are completed. Similar to what the contractors have done for the rectification works in common areas, we consider that there are merits in conducting a trial for works inside flats to test contractors' method and the arrangements on a small scale first. As works in the common areas of Kwai Yuet House at Lower Ngau Tau Kok Estate Phase 1 had been substantially completed, we announced on 11 October 2016 that a trial would be conducted there starting from 17 October 2016. Works inside flats for the rest of the affected PRH developments will be rolled out subsequently in light of the experiences of the trial works at Kwai Yuet House.
- 7. As the furnishings and pipe routings inside individual flats vary from one to another, there are a number of technical issues which must be resolved before works inside flats can start. Having discussed with the contractors and consulted the WA, we have worked out the arrangements for works inside flats

2

¹ To avert fire risk and nuisance to tenants arising from soldering pipe joints, and in line with HA's past practice in conducting replumbing works for existing estates, the four contractors have been using compression joints for connecting water pipes in the rectification works in the common areas, except at locations where soldering cannot be avoided due to site constraints.

as follows -

- (a) **Opt out:** an issue which has been raised by tenants is whether they can opt out of the works inside flats. In considering this issue, HA needs to take into account HA and tenants' legal obligations under the Waterworks Ordinance/Waterworks Regulation. Accordingly, we will require the contractors to replace the non-compliant pipes for every domestic unit of the 11 affected PRH developments. However, in practice, we do appreciate that some tenants may not be able to make arrangements to tie in with contractors' works programmes for various reasons. Such special cases will be dealt with after the contractors have completed other units of the same estate. For such tenants, HA and its contractors will continue to contact and persuade the tenants to allow contractors to carry out the works inside flats for health consideration.
- (b) **Pipe routing:** to avoid or minimise damage to tenants' furnishings, the contractors will adopt the piping's existing routing as far as practicable. If this is impracticable, a new routing would be adopted. contractors will aim to complete works for each flat within one day as far as practicable, provided that tenants' existing furnishings are not extensive and the weather condition is favourable for works at external walls of the flat. The reinstatement of furnishings may be arranged on another day where necessary. For cases where the furnishings and/or pipe routings are more sophisticated, the works may take one more day. The water supply to the domestic unit where works are carried out will be temporarily suspended from 9 am to 6 pm, save for special circumstances where extension of time is necessary. The contractors will communicate with tenants on the arrangements before works start. HA has asked the contractors to make good any damages to the furnishings as a consequence of the rectification works and to handle any claims for compensation by tenants.
- 8. Since the trial for works inside flats started at Kwai Yuet House in Lower Ngau Tau Kok Estate Phase 1 on 17 October 2016, the contractor has been contacting tenants for household visits to work out the detailed arrangements for the works and to schedule a time which is convenient to tenants for carrying out the works inside their flats. As at 25 November 2016, the contractor has completed works for 65 flats. So far, the contractor has not encountered major problems in conducting works inside flats. Yet, some tenants have expressed their unwillingness to replace the non-compliant water pipes inside their flats. For these tenants, we will, as we mention in paragraph 7(a) above, continue to maintain dialogue with them in a bid to seek their cooperation and understanding in getting the works done.

- 9. The trial for works inside flats will unavoidably cause inconvenience to tenants (e.g. temporary suspension of water supply, mounting of gondolas on external walls, use of passenger lifts to convey materials during non-peak hours and use of some public space in the estate for workshops, etc.). We have asked the contractor to minimise the nuisance and inconvenience as far as practicable and the following measures have been put in place for better communication with tenants
 - (a) newsletters providing details of the trial (e.g. the scope, dates, water suspension time etc.) have been distributed to the tenants concerned and notices have been posted in the lobbies of the estate;
 - (b) a briefing for the Estate Management Advisory Committee has been held;
 - (c) ambassadors have been deployed to answer tenants' enquiries; and
 - (d) a hotline has been set up to answer tenants' enquiries (from 9 am to 6 pm, Monday to Saturday).
- 10. Installation of water filters and provision of temporary water supply through standpipes and water points on each floor of the 11 affected PRH developments are measures which have been implemented to assist tenants in gaining access to safe drinking water. These measures will continue to be in force until the rectification works for both the common areas and inside flats are completed. After works inside flats are completed, water sampling tests (covering various parameters including lead) will be conducted in accordance with the Water Supplies Department (WSD)'s Circular Letter No. 5/2015 and 1/2015. Subject to satisfactory water test results and the progress of works, water filters will be removed and temporary water supply will be withdrawn in stages.
- 11. As reported earlier, the contractors have been replacing or cleaning filter cartridges regularly in accordance with the manufacturer's instructions². For households with whom we have had difficulty in getting in touch, the contractors have been trying to contact them outside working hours including on Sundays, and will continue to do so. HA and the contractors will also continue to encourage households which have not installed water filters (including those

4

² For the households with filters installed in Wing Cheong Estate and Tung Wui Estate, Paul Y. General Contractors Limited cleans the filter cartridges about once every three months, and replaces the filter cartridges once within 12 months' time. Since the installation of filters, Paul Y. has cleaned the filter cartridges for these households three times already, and it has started replacing the filter cartridges for these households since September 2016. The remaining three contractors replace the filter cartridges for the households in their affected PRH developments about once every six months. Since filters were installed in the affected PRH developments at different times, the timing for replacement of the filter cartridges varies from one estate to another. The latest round of filter cartridge replacement is in progress.

who have refused to install filters) to consider installing filters by posting notices at the lobbies and distributing newsletters to tenants' mailboxes.

- 12. As for non-domestic units within the 11 affected PRH developments, rectification works will also be carried out to the extent that the pipes were installed by HA's contractors. Unlike domestic units where pipes inside units were installed by HA's contractors, for non-domestic units, HA's contractors installed various types of water supply connections (e.g. water points/plugged off water pipes/toilets, etc.), while tenants often installed/varied pipework inside the unit. Given that the pipework inside non-domestic units is more complex than that in domestic units, and having considered the liability and maintenance issues as well as the possibility that some tenants may not prefer to have rectification works inside their premises, we will request the HA's contractors to only replace those sections of the pipework which were installed by them. For those sections of pipework which were installed or varied by tenants themselves, we are liaising with the relevant bureaux/departments to see if they need to make separate arrangements for special cases.
- 13. HA will continue to monitor the progress of rectification works and liaise with WA and contractors to ensure that the works can be completed as soon as possible.

Enhancing HA's Quality Assurance Mechanism

- 14. HA has all along had a risk assessment system for building materials. The "excess-lead-in-water" incident has revealed that there is room for enhancement in how we identify risks and classify how such risks should be followed up. We have already started an exercise to strengthen our risk assessment of building materials.
- 15. The exercise covers all building materials used in architectural (1,000+), building services (600+) and structural works (60+). Making reference to ISO 31000^3 , the risk assessment on materials is conducted based on the following framework
 - (a) for each of the materials, risk is rated in terms of a combination of the "Likelihood" of occurrence and the "Consequence" of an event;
 - (b) the total risk score/level is derived by multiplying the "Likelihood" and "Consequence" aspects. Follow-up actions will be taken based on the

5

³ ISO 31000: Risk Management – Principles and Guidelines is an international standard that provides principles and generic guidelines on risk management. It establishes a number of principles that need to be satisfied before risk management will be effective.

degree of the total risk level of the material; and

- (c) a time factor is also included to identify the possible point at which the event may occur so as to target control measures at the particular time during the building construction period. These time factors are "Purchasing", "Delivery", "Storage Control" and "Use (Installation)".
- 16. We have engaged the Hong Kong Quality Assurance Agency as an independent party to assess whether the adopted risk assessment methodology aligns with the risk management requirements as set out in the ISO 31000 standard. We have also been engaging other stakeholders (e.g. contractors, relevant Government departments, trade associations/institutions, academia, etc.) to seek their advice on areas concerning safety and health. The risk assessment exercise is targeted to be completed by end-2016. Staged implementation of materials control measures will begin thereafter.
- 17. The final results of the risk assessment will then be incorporated into the quality control system on materials compliance checking and monitoring which will include the updating of the contract requirements, specifications, technical guides and site inspection procedures. The enhanced risk assessment regime will be subject to review on a regular basis and where necessary.

Actions against contractors

- 18. Since the "excess-lead-in-water" incident, HA has been taking actions against the contractors for their liabilities under the contracts. Apart from installing temporary water points on each floor and filters for affected households free of charge, as well as replacing the non-compliant pipes as mentioned in paragraphs 2-12 above, the contractors have also taken the following measures:
 - (a) providing each household of the 11 PRH developments with a subsidy of \$660 for paying water and sewage charges within three years starting from 1 January 2016; and
 - (b) providing HA with a performance bond of \$5,000 per flat. In the event that the contractors are in default of performing any of the relief measures, HA can seek recovery from the guarantor. All four contractors concerned have already provided a performance bond undertaking to HA in respect of each of the affected PRH developments.

19. Following the publication of the Commission of Inquiry into Excess Lead Found in Drinking Water (COI) report, HA's Tender Committee (TC) has discussed and considered whether any further follow-up action needed to be TC noted that all the committed actions by the four contractors concerned had been carried through and all the regulatory actions previously imposed against the contractors and other related parties had been completed. Meanwhile, the performance of the contractors in carrying out the interim measures and permanent rectification works would continue to be closely monitored. Further regulatory actions may be imposed if the main contractors' performance is not satisfactory. We will also keep in view the relevant Further actions against implicated parties may be criminal investigation. considered upon completion of the criminal investigations and legal proceedings, if any. We will report to TC at an appropriate juncture on the contractors' performance and take follow-up actions as appropriate.

Water Sampling Test Results for PRH Estates

- 20. Since the "excess-lead-in-water" incident, we have been updating the public through various channels on the latest developments of water sampling for PRH estates and the various follow-up actions. When the water sampling exercise was conducted for PRH estates from July to November 2015, information on the water sampling results was made public once it became available in order to keep the public and affected tenants abreast of the extent of excess lead in drinking water in PRH estates.
- As we reported before, while the initial focus was on the quality of drinking water supplied to domestic tenants, that supplied to non-domestic tenants had not been neglected. Samples were subsequently taken from the non-domestic facilities located within PRH estates in a more systematic manner. As the number of samples taken from non-domestic premises was only finalised in March 2016, we took the earliest opportunity to update the HA on the confirmed number of samples (including these non-domestic samples). The same information was also provided to the LegCo House Committee in July 2016.
- 22. In reviewing the follow-up actions of PRH's water sampling tests for lead, Audit Commission (AC) has found a few discrepancies between the source data and the information concerning water sampling of non-domestic units that was reported to HA and LegCo in March 2016 and July 2016 respectively. The discrepancies are set out below
 - (a) Kai Ching Estate: the total number of samples with excess lead should be 9 instead of 7;

- (b) Yan On Estate: the total number of samples taken should be 73 instead of 74;
- (c) Shek Kip Mei Estate Phase 2 (Mei Wui House, Mei Leong House): the total number of samples taken should be 54 instead of 59; and
- (d) Shek Kip Mei Estate Phase 2 Ancillary Facilities Block: the total number of samples taken should be 12 instead of 6.
- 23. Taking into account the two omitted water samples taken at the non-domestic units of Kai Ching Estate sharing the same water supply system with the domestic units already found with excess lead (i.e. item 22(a) above), the total number of water samples which were found to have excess lead should be 93 instead of 91. However, this does not affect the categorisation of Kai Ching Estate as an affected estate because the two non-domestic samples were taken after Kai Ching Estate was declared as an affected estate. As AC mentioned in the Audit Report published on 23 November 2016, notwithstanding the discrepancies identified, the total number of affected PRH developments remained unchanged. Items 22(b) to (d) above are mainly concerned about inappropriate categorisation. The correct water sampling test tallies are provided at the **Annex** for Members' reference.
- 24. In spite of the above discrepancies, the following information which has been made public remains unchanged:
 - (a) total number of samples taken for PRH estates: 7,456;
 - (b) total number of samples taken for PRH estates completed before 2005: 2,635;
 - (c) total number of samples taken for PRH estates completed in and after 2005: 4,821; and
 - (d) classification of affected and unaffected PRH estates.
- 25. We have informed the HA and the public of and rectified the discrepancies. We will, as recommended by the AC, strengthen data validation in collaboration with the WSD to ensure that information provided to HA/LegCo is accurate.

Transport and Housing Bureau December 2016

Systematic water sampling test results for PRH developments completed in and after 2005

(a) Water samples with excess lead

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken	No. of samples with excess lead
1	Kwai Luen Estate Phase 2 (Luen Yat House, Luen Yuet House)	2014	1 507	Shui On Building Contractors Limited	44	5
2	Kai Ching Estate	2013	5 204	China State Construction Engineering (Hong Kong) Limited	121	9
3	Wing Cheong Estate	2013	1 488	Paul Y. General Contractors Limited	46	1
4	Lower Ngau Tau Kok Estate Phase 1 (Kwai Leung House, Kwai Yuet House, Kwai Hin House, Kwai Sun House, Kwai Fai House)	2012	4 238	Yau Lee Construction Company Limited	131	6
5	Shek Kip Mei Estate Phase 2 (Mei Wui House, Mei Leong House)	2012	1 558	Yau Lee Construction Company Limited	54	5
6	Tung Wui Estate (Wui Sum House, Wui Yan House)	2012	1 333	Paul Y. General Contractors Limited	52	4
7	Hung Hom Estate Phase 2 (Hung Yat House, Hung Yan House, Hung Yiu House)	2011	1 938	China State Construction Engineering (Hong Kong) Limited	74	16

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken	No. of samples with excess lead
8	Yan On Estate (Yan Hei House, Yan Yuet House, Yan Chung House)	2011	2 587	Yau Lee Construction Company Limited	73	5
9	Choi Fook Estate (Choi Lok House, Choi Sin House, Choi Hay House)	2010	2 524	Yau Lee Construction Company Limited	92	13
10	Un Chau Estate Phase 2 and 4 (Un Lok House, Un Nga House, Un Chi House, Un Hei House, Un Kin House)	2008	3 533	Yau Lee Construction Company Limited	135	19
11	Ching Ho Estate Phase 1 (Ching Chung House, Ching Yu House, Ching Hin House)	2008	3 167	Yau Lee Construction Company Limited	145	10

(b) Water samples that comply with the World Health Organisation (WHO)'s Provisional Guideline Value (PGV) $\,$

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
1	Cheung Lung Wai Estate, Cheung Lung Lane and Cheung Lung Wai Estate Ancillary Facilities Block	2015	1 358	Yau Lee Construction Company Limited	49
2	Hung Fuk Estate Phase 1 and 2 (Hung Foon House, Hung Yan House, Hung Hei House, Hung Lok House, Hung Fuk Shopping Centre and Ancillary Facilities Block)	2015	2 097	Hsin Chong Construction Company Limited	163
3	Hung Fuk Estate Phase 3 (Hung Long House, Hung Yat House, Hung Yuet House, Hung Cheong House, Hung Shing House)	2015	2 808	Yau Lee Construction Company Limited	
4	Shui Chuen O Estate Phase 1 (Ching Chuen House, Long Chuen House, Yan Chuen House, Hei Chuen House) (Note)	2015	3 039	China State Construction Engineering (Hong Kong) Limited	59
5	Mei Tung Estate (Mei Tak House)	2014	990	Able Engineering Company Limited	26
6	Yee Ming Estate	2014	2 059	Hanison Construction Company Limited	108
7	Tak Long Estate, carpark block and kindergarten	2014	8 164	Yau Lee - Hsin Chong Joint Venture	208

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
8	Fung Wo Estate	2013	1 607	Hsin Chong Construction Company Limited	54
9	Cheung Sha Wan Estate and Cheung Sha Wan Estate Ancillary Facilities Block	2013	1 390	China State Construction Engineering (Hong Kong) Limited	51
10	Lung Yat Estate and Lung Yat Community Hall	2013	990	Shui On Building Contractors Limited	39
11	Mei Tin Estate (Mei Chuen House) and free standing block	2013	1 216	Hsin Chong Construction Company Limited	36
12	Shek Lei (II) Estate (Shek Foon House)	2013	839	Hip Hing Construction Company Limited	26
13	Ching Long Shopping Mall	2013	-	Zone A: China State Construction Engineering (Hong Kong) Limited Zone B: Yau Lee - Hsin Chong Joint Venture	20
14	Shek Kip Mei Estate Phase 5 (Mei Yick House, Mei Yin House, Mei Sang House, Mei Shing House)	2012	2 496	Shui On Building Contractors Limited	75
15	Un Chau Estate Phase 5 (Un Mun House, Un Wai House, Un Yat House) and Un Him House (i.e. Ancillary Facilities Block)	2012	1 486	China State Construction Engineering (Hong Kong) Limited	55

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
16	Domain and Yau Tong Community Hall	2012	-	China State Construction Engineering (Hong Kong) Limited	8
17	Choi Fook Estate (Choi Foon House)	2011	915	Hsin Chong Construction Company Limited	27
18	Choi Tak Estate (Choi Yan House, Choi Yee House)	hoi Yan House, Choi Yee House) Construction Company Limited		41	
19	Kwai Luen Estate Phase 1 (Luen Yan House, Luen Hei House)	`		43	
20	Mei Tung Estate (Mei Yan House)	2010	799	China State Construction Engineering (Hong Kong) Limited	31
21	Choi Tak Estate (Choi Chun House, Choi King House, Choi Leung House, Choi Yin House) and Choi Tak Shopping Centre	2011	2 704	China State Construction Engineering (Hong Kong) Limited	83
22	Shatin Pass Estate (Wo Tin House, Shun Tin House)	2011	1 278	Chevalier (Construction) Company Limited	53
23	Yau Lai Estate Phase 5 (Cheuk Lai House, Yung Lai House) and carpark block	2011	2 002	Shui On Building Contractors Limited	39
24	Yau Lai Estate Phase 6 (i.e. Yau Lai Shopping Centre)	2011	-	Shui On Building Contractors Limited	4
25	Shin Ming Estate (Shin Chi House, Shin Lai House)	2011	1 974	Shui On Building Contractors Limited	50
26	Tin Ching Estate Tin Ching Amenity and Community Building	2011	-	Paul Y. General Contractors Limited	24
27	Chai Wan Estate (Wan Poon House, Wan Ying House)	2010	1 600	Nishimatsu Construction Co., Limited	46

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
28	Choi Tak Estate (Choi Shing House, Choi Shun House)	2010	1 462	Hanison Construction Company Limited	69
29	Upper Ngau Tau Kok Estate Phase 2 and 3 (Sheung Hing House, Sheung Shing House, Sheung Fu House, Sheung Wing House, Sheung Hong House, Sheung Tai House), Upper Ngau Tau Kok Shopping Centre and Integrated Service Centre	2009	4 584	Paul Y. General Contractors Limited	124
30	Tin Ching Estate Phase 3 (Ching Moon House, Ching Hei House, Ching Yuet House)	use, Ching Hei House, Contractors Limited		65	
31	Shek Kip Mei Estate Phase 1 (Mei Yue House, Mei Ying House)	2006	2 033	Paul Y. General Contractors Limited	55
32	Sau Mau Ping (South) Estate (Sau Ho House, Sau Wong House)	2009	1 598	Chatwin Engineering Limited	130
33	Sau Mau Ping (South) Estate (Sau Mei House, Sau Tak House, Sau Sin House)	2009	2 397	Hanison Construction Company Limited	
34	Upper Wong Tai Sin Estate (Wing Sin House)	2009	714	Chun Wo Construction and Engineering Company Limited	22
35	Yau Lai Estate Phase 4 (Tsui Lai House, Hong Lai House, Yan Lai House)	2009	2 369	Shui On Building Contractors Limited	121
36	Yau Lai Estate Phase 3 (Ying Lai House, Fung Lai House)	2008	1 598	China State Construction Engineering (Hong Kong) Limited	
37	Shek Mun Estate Phase 1 (Kin Shek House, Mei Shek House) and supermarket	2009	1 958	Paul Y. General Contractors Limited	45

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
38	Lam Tin Estate (Lam Fai House, Lam Tai House, Lam Bik House, Lam Wai House)	2009	3 036	Shui On Building Contractors Limited	102
39	Mei Tin Estate Phase 3 (Mei Lok House, Mei Mun House, Mei Ting House) and Mei Tin Community Hall	2008	2 333	Hanison Construction Company Limited	71
40	Tin Ching Estate Phase 1 (Ching Pik House, Ching Hoi House) and Tin Ching Community Hall	2008	1 918	China State Construction Engineering (Hong Kong) Limited	98
41	Tin Ching Estate Phase 2 (Ching Choi House, Ching Wan House), Tin Ching Shopping Centre and Tin Ching Ancillary Facilities Block	2008	1 918	Nishimatsu Construction Co., Limited	
42	Choi Ying Estate Phase 1 (Ying Fu House, Ying On House)	2008	1 598	China State Construction Engineering (Hong Kong) Limited	137
43	Choi Ying Estate Phase 2 (Ying Hong House, Ying Lok House, Ying Shun House)	2008	2 397	China State Construction Engineering (Hong Kong) Limited	
44	Choi Ying Estate Phase 3 (i.e. Choi Ying Place)	2008	-	Shui On Building Contractors Limited	
45	Ching Ho Estate Phase 1 Ching Ho Shopping Centre	2008	-	Yau Lee Construction Company Limited	3

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
46	Ching Ho Estate Phase 2 (Ching Ping House, Ching Yun House)	2008	1 598	China State Construction Engineering (Hong Kong) Limited	54
47	Tung Wui Estate Tung Tau Community Centre	2012	-	Paul Y. General Contractors Limited	1
48	Shek Kip Mei Estate Phase 2 Ancillary Facilities Block	2012	-	Yau Lee Construction Company Limited	12
49	Lower Ngau Tau Kok Estate Phase 1 Lower Ngau Tau Kok Estate Plaza	2012 - Yau Lee Construction Company Limited		3	
50	Yan On Estate Yan On Shopping Centre	ropping 2011 - Yau Lee Construction Company Limited		2	
51	Oi Tung Estate (Oi Yat House)	2008	716	Nishimatsu Construction Co., Limited	23
52	Shek Pai Wan Estate Phase 2 (Pik Shan House, Pik Yuen House, Pik Wai House, Pik Luk House)	2007	2 398	Hanison Construction Company Limited	95
53	Lei Yue Mun Estate Phase 2 (Lei Lung House)	2007	799	Paul Y. General Contractors Limited	27
54	Shek Lei (II) Estate (Shek Wai House, Shek Yi House)	2007	1 598	Nishimatsu Construction Co., Limited	48
55	Ching Ho Estate Phase 3 (Ching Chak House, Ching Long House, Ching Chiu House)	2006	2 397	Shui On Building Contractors Limited	81
56	Kwai Chung Estate (Pak Kwai House, Hop Kwai House)	2008	1 983	Yau Lee Construction Company Limited	81

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
57	Mei Tin Estate Phase 1 and 2 (Mei Sau House, Mei Lai House, Mei King House, Mei Chi House) and Mei Tin Shopping Centre	2005	3 164	Nishimatsu Construction Co., Limited	95
58	Hoi Lai Estate Phase 3 (i.e. Hoi Lai Shopping Centre) and Phase 4 (Hoi Shui House)	2005	558	China State Construction Engineering (Hong Kong) Limited	29
59	Kwai Chung Estate Phase 3 (Chui Kwai House, Pik Kwai House, Luk Kwai House)	2005	2 742 Yau Lee Construction Company Limited		84
60	Hin Yiu Estate (Hin Yiu House)	2005	799 Shui On Building Contractors Limited		26
61	Shek Yam Estate Phase 5 (Lai Shek House)	2005	340	Hanison Construction Company Limited	9
62	Kwai Shing (East) Estate (Shing Wo House)	2003	362	Hsin Chong Construction Company Limited	59
63	Tsz Lok Estate (Lok Foon House)	2003	265	China State Construction Engineering (Hong Kong) Limited	23
64	Lok Fu Estate (Lok Tsui House)	1994	360	Hung Wan Construction Co Ltd	16
65	Yat Tung (II) Estate (Mei Yat House, Mun Yat House, Kui Yat House)	2005	2 782	Yau Lee Construction Company Limited	108
66	Lei Muk Shue Estate Phase 3 (Chui Shue House, Wing Shue House) and Lei Muk Shue Shopping Centre	2005	1 983	Hip Hing Construction Company Limited	66
67	Lei Muk Shue Estate Phase 4 (Hong Shue House, Lok Shue	2005	1 918	China State Construction Engineering (Hong	54

	Name of PRH development	Year of completion	No. of units	Main contractor	No. of samples taken
	House, Kin Shue House)			Kong) Limited	
68	Yau Lai Estate Phase 1 (Bik Lai House, Sau Lai House, Yi Lai House, Nga Lai House, Chi Lai House, Yat Lai House)	2005	2 550	Leighton Contractors (Asia) Limited	78
69	Shek Pai Wan Estate Phase 1 (Pik Long House, Pik Yuet House, Pik Ngan House, Pik Fai House) and Shek Pai Wan Shopping Centre	2005	2 877	Shui On Building Contractors Limited	92
70	Kwai Chung Estate Phase 3 Kwai Chung Shopping Centre	2005	-	Yau Lee Construction Company Limited	6
71	Kwai Chung Estate Phase 4 (Chin Kwai House, Tsz Kwai House)	2005	1 983	China State Construction Engineering (Hong Kong) Limited	70
72	Kwai Chung Estate Phase 5 (Hiu Kwai House, Ying Kwai House, Yuk Kwai House, Nga Kwai House, Yat Kwai House)	2005	4 515	Hip Hing Construction Company Limited	152

(Note) One sample taken from a vacant unit at Hei Chuen House of Shui Chuen O Estate was found to have a lead level of 14 micrograms per litre, which slightly exceeded WHO's PGV. The water samples taken from the rest of the three domestic blocks did not exceed the value. WSD took more water samples from Hei Chuen House for testing to ascertain the situation. After analysis, it was concluded that the water sample which exceeded the value might have been affected by the environment.

Screening test results for PRH estates completed before 2005

(144 PRH estates involving 2 635 water samples)

Water samples that comply with WHO's PGV

		at compry w						
Tsui Ping	Lee On	Butterfly	Choi Fai	Sai Wan	Choi Yuen	Tin Yan	Tsz Lok	Oi Tung
(South)	Estate	Estate	Estate	Estate	Estate	Estate	Estate	Estate
Estate								
Kwai	Kin Ming	Tin Yuet	Po Tat	Lei Yue	Tin Heng	Tin Chak	Sau Mau	Fu Tai
Shing	Estate	Estate	Estate	Mun	Estate	Estate	Ping Estate	Estate
(East)				Estate				
Estate								
Wang Tau	Ap Lei	Lei Muk	Chun	Pak Tin	Ka Fuk	On Yam	Sheung Tak	Cheung
Hom	Chau	Shue (I)	Shek	Estate	Estate	Estate	Estate	Hang
Estate	Estate	Estate	Estate					Estate
Yiu Tung	Tsz Man	Wah Sum	Shek Lei	Tin Wan	Ko Yee	Wan Hon	Sheung Lok	Tsz Ching
Estate	Estate	Estate	(I) Estate	Estate	Estate	Estate	Estate	Estate
Listate	Listate	Lstate	(1) Estate	Listate	Listate	Listate	Listate	Listate
Kwai	Chung On	Ho Man Tin	Ko	Upper	Tin Shui (II)	Tai Wo Hau	Cheung	Hau Tak
Fong	Estate	Estate	Cheung	Wong Tai	Estate	Estate	Hong Estate	Estate
Estate			Court (the	Sin Estate				
			PRH					
			portion)					
Shun Tin	Wan Tsui	Sun Chui	Mei Lam	Kwong	Shek Kip	Lung Hang	Lei Muk	Hing Wah
Estate	Estate	Estate	Estate	Fuk Estate	Mei Estate	Estate	Shue (II)	(I) Estate
Listate	Listate	Listate	Listate	T dix Estate	Wici Estate	Listate	Estate	(1) Listate
							Listate	
Shek Wai	Oi Man	Yau Oi	Lai Kok	Sam Shing	Kwai Shing	Lek Yuen	Lai King	Kai Yip
Kok	Estate	Estate	Estate	Estate	West Estate	Estate	Estate	Estate
Estate								
Un Chau	Siu Sai	Hing Man	Chuk	Cheung	Sha Kok	Tai Yuen	Choi Wan (I)	Cheung
Estate	Wan	Estate	Yuen	Ching	Estate	Estate	Estate	Wang
	Estate		(South)	Estate				Estate
			Estate					
Shui Pin	Ping Shek	Ma Tau Wai	Shek Lei	Tsz Hong	Wah Lai	Kwai	Ping Tin	Lok Fu
Wai Estate	Estate	Estate	(II) Estate	Estate	Estate	Chung	Estate	Estate
						Estate		
Shek Yam	Wah Fu	Fu Shan	Lai Yiu	Tin Tsz	Hing Tung	Tin Shui (I)	Wu King	Tin Yiu (I)
						` ′	•	` '
East	(II) Estate	Estate	Estate	Estate	Estate	Estate	Estate	Estate
Estate								
					•			

Tin Yiu (II) Estate	Wah Fu (I) Estate	Mei Tung Estate	Yat Tung (I) Estate	On Ting Estate	Tai Hing Estate	Wo Che Estate	Shun On Estate	Choi Hung Estate
Lung Tin Estate	On Tin Estate	Yau Tong Estate	Cheung Shan Estate	Fuk Loi Estate	Hoi Lai Estate	Tai Hang Tung Estate	Lower Wong Tai Sin (II) Estate	Ma Hang Estate
Shek Yam Estate	Tin Wah Estate	Upper Ngau Tau Kok Estate	Lok Wah (North) Estate	Yat Tung (II) Estate	Fu Cheong Estate	Tin Yat Estate	High ProsperityTerr ace	Easeful Court
Shek Lei Interim Housing	Hong Tung Estate	Fu Tung Estate	Ming Tak Estate	Shun Lee Estate	Grandeur Terrace	Po Tin Estate	Kam Peng Estate	Ngan Wan Estate
Lok Wah (South) Estate	Yue Wan Estate	Nga Ning Court	Tsui Lok Estate	Kai Tin Estate	Lai On Estate	Kwong Tin Estate	Cheung Kwai Estate	Chak On Estate
Sun Tin Wai Estate	Wo Lok Estate	Hung Hom Estate	Choi Wan (II) Estate	Fortune Estate	Nam Shan Estate	Model Housing Estate	Hing Wah (II) Estate	Long Bin Interim Housing