把鄉村旱廁改建為沖水式廁所 第七期(最後一期)工程 Conversion of Aqua Privies into Flushing Toilets – Phase 7 (the Final Phase)

在策劃和建造上所遇到的困難(一) Problems Encountered at Planning and Construction Stages (1)

地界太接近私人土地, 在規劃及建造上受限 制。

Site boundary too close to the adjacent private lot, thus posing limitations on planning and construction works



在策劃和建造上所遇到的困難(二) Problems Encountered at Planning and Construction Stages (2)

位於偏遠地區,在運 送物料及設備上需額 外工期。

Located at remote areas, required extra time and resources to deliver the equipment and materials





在策劃和建造上所遇到的困難(三) Problems Encountered at Planning and Construction Stages (3)

接近斜坡及樹木,令勘察及規劃時間增加。
 Close to adjacent slope and trees, thus leading to extra investigation and planning time for the projects





改善重點(一)

Key Improvements (1)

美化外觀Attractive appearance



改善前 Before Improvement



改善後 After Improvement

改善重點(二) Key Improvements (2)

• 寬濶空間符合現時標準
Spacious accommodation to meet current standard



改善前 Before Improvement



改善後 After Improvement

改善重點(三) Key Improvements (3)

• 改善通風和照明(包括室內外照明) Improved ventilation and lighting



改善前 Before Improvement



改善後 After Improvement

改善重點(四) Key Improvements (4)

• 環保設備 Environmentally friendly features



感應式水龍頭 Sensor type tap



感應式燈光控制 Occupancy sensor control for lighting



雙冲水量控制 Dual flush control

改善重點(五)

Key Improvements (5)

• 改善衞生環境設施(加設沖水及洗滌設備)
Better hygiene facilities
(with flushing system and washing facilities)









改善前 Before Improvement

改善後 After Improvement

改善重點(六)

Key Improvements (6)

• 其他改善地方 Other improvements



呼救按鈕 Call button





爲長者所設的扶手 Hand rail for aged



嬰兒換尿片枱 Baby changing counter

造價預算 Estimated Cost

- 工程費用估計約3.8億元 Total Cost: around \$380M
- 第一類及第三類廁所: 約一百萬元至二百 多萬元 Type 1 and Type 3 Toilets: from \$1M to \$2M
- 第二類廁所: 約二百萬元至三百多萬元 Type 2 Toilets: from \$2M to \$3M