

**Shatin Area 14 B Phase 2**  
**Summary of Chi Shing's Concrete Coring Invoices**

Source	Chi Shing's Concrete Coring Invoices						Acer Pacific's Core Test Report
Pile No.	No. of Core Holes	Coring Length (m)				Lengths of Cores Extracted (m)	Length of Concrete Cores Submitted (m)
		1	2	3	4		
<b>Block D</b>							
D/1	2	43.27	17.20	-	-	60.47	43.01
D/2	No record	-	-	-	-	-	42.22
D/3	-	-	-	-	-	-	-
D/4	2	43.83	14.80	-	-	58.63	40.20
D/5	-	-	-	-	-	-	-
D/6 <sup>△</sup>	2	21.50	36.48	-	-	57.98	41.10
D/7	2	5.60	45.60	-	-	51.20	42.76
D/8 <sup>△</sup>	1	45.52	-	-	-	45.52	44.87
D/9	2	43.02	24.91	-	-	67.93	42.38
D/10	4	26.62	44.26	19.10	17.50	107.48	42.87
D/11	-	-	-	-	-	-	-
D/12	4	9.06	1.60	44.96	18.29	73.91	40.93
D/13	4	49.40	11.08	22.24	49.00	131.72	43.88
D/13TN	-	-	-	-	-	-	44.93
D/14	2	10.03	45.08	-	-	55.11	40.44
D/15 <sup>△</sup>	1	43.74	-	-	-	43.74	40.49
D/16	-	-	-	-	-	-	-
D/17	1	44.04	-	-	-	44.04	41.79
D/18	-	-	-	-	-	-	-
<b>Block E</b>							
E/1	-	-	-	-	-	-	-
E/2	-	-	-	-	-	-	-
E/3 <sup>△</sup>	-	-	-	-	-	-	-
E/4 <sup>△</sup>	1	41.30	-	-	-	41.30	40.58
E/5 <sup>△</sup>	-	-	-	-	-	-	-
E/6	-	-	-	-	-	-	-
E/7	-	-	-	-	-	-	-
E/8	-	-	-	-	-	-	-
E/9	1	46.59	-	-	-	46.59	45.75
E/10	-	-	-	-	-	-	-
E/11 <sup>△</sup>	-	-	-	-	-	-	-
E/12	-	-	-	-	-	-	-
E/13	-	-	-	-	-	-	-
E/14	-	-	-	-	-	-	-
E/15	-	-	-	-	-	-	-
E/16	-	-	-	-	-	-	-
E/17 <sup>△</sup>	-	-	-	-	-	-	-
E/18 <sup>△</sup>	-	-	-	-	-	-	-

Remark:

<sup>△</sup> Actual pile length is shorter than recorded length by at least 10 m.

Source of information : Strickland Report