CB(1)756/10-11(01)

政府總部

發展局

工務科

香港花園道英利大厦



Works Branch
Development Bureau
Government Secretariat
Murray Building, Carden Road,
Hong Kong

准語 Tel No. :2848 2106

供真 Fax No.: 2521 9682

本局檔號 Our Ref. : DEVB(CR)(W) 1-5/4 Pt. II

來函檔號 Your Ref. :

3rd floor, Citibank Tower,
3 Garden Road,
Hong Kong Legislative Council Secretariat

(Attn: Mr Stephen LAM)

(Fax: 2869 6794)

Dear Mr Lam.

8 December 2010

Issues arising from the fatal falling gate incident at the Hang Ngai Manufacturing and Hostel in Hung Hom

During the LegCo Development Panel meeting on 26 May 2009, the Administration agreed that once the judicial proceedings of the incident at the Hang Ngai Manufacturing and Hostel in Hung Hom were concluded, the Administration would provide the investigation report to Members.

The Coroner's Court had held a hearing on this case and concluded on 11 October 2010 that the cause of death was an accident. The Government had also taken prosecution action against the contractors responsible for the works, and the case was concluded on 8 December. As hearings related to the incident have been concluded, the Architectural Services Department has uploaded its investigation report today onto its website (<a href="http://www.archsd.gov.hk/archsd.home01.asp?Path_Lev1=5&Status="https://www.archsd.gov.hk/archsd.home01.asp?Path_Lev1=5&Status="https://www.archsd.gov.hk/gia/general/201012/08/P2\$1012080221.htm).

Grateful if you would bring the above to Members' attention.

Yours faithfully,

(David Tong) for Secretary for Development