

Panel on Housing

List of follow-up actions

(position as at 1 December 2015)

Subject	Date of meeting	Follow-up action required	Administration's response
<p>1. Head 711 projects</p> <p>(a) Footbridge Link at Sau Ming Road, Kwun Tong</p> <p>(b) Public Transport Interchange ("PTI") at Pak Wan Street, Sham Shui Po</p>	<p>1.6.2015</p>	<p>The Administration to provide in its submission on item (b) to the Public Works Subcommittee ("PWSC") information on –</p> <p>(a) the plot ratios of the public housing developments to be provided above the proposed PTI, as well as in other phases of the public housing redevelopment at Pak Tin Estate, with explanation on whether and how the plot ratios have optimized the land use at the sites;</p> <p>(b) the welfare facilities to be provided along with the public housing developments above the PTI, and the scale and floor areas of these facilities vis-à-vis the entire site and the composite development thereat; and</p> <p>(c) the ventilation design of the PTI to ensure air and noise nuisances arising from the PTI to the residents of the public housing developments above and the local community at large would be minimized.</p>	<p>The requested information to be provided to PWSC.</p>

<b>Subject</b>	<b>Date of meeting</b>	<b>Follow-up action required</b>	<b>Administration's response</b>
2.1 Incidents of excess lead in drinking water in public housing estates	2.11.2015	<p>The Administration to provide information on the following –</p> <ul style="list-style-type: none"><li>(a) in connection with the six building contractors which were found to have been involved in the construction of the 11 public rental housing ("PRH") estates where excessive lead content was found in drinking water, the number of plumbing subcontractors commissioned by these contractors in these projects, and the number of PRH estates completed in or after 2005 where these plumbing subcontractors were commissioned for the construction works;</li><li>(b) whether the affected tenants in the four PRH estates where excessive lead content was found in drinking water and where connection pipes had been extended from the roof-top water tanks to each floor of the building obtained fresh water from these connection pipes or from the household water taps direct upon installing water filters;</li><li>(c) the follow up plans on board and their progress made for the children who showed signs of developmental delay; and</li></ul>	Response awaited

<b>Subject</b>	<b>Date of meeting</b>	<b>Follow-up action required</b>	<b>Administration's response</b>
2.2 Public Housing Construction Programme 2015-16 to 2019-20		(d) whether the Administration would consider providing free blood tests to children who were under eight years of age when moving into the PRH estates concerned.  The Administration to provide information on the latest position of the 2 300 units under the Hung Shui Kiu Area 13 Phase 3 project which were scheduled for completion in 2014-2015.	Response awaited