


Boulder Stabilization Works at Ha Keng 在下徑的大石加固工程





Locations of the Potentially Unstable Boulders and Man-made Slopes
有潛在不穩之大石及人造斜坡的位置



Western Natural Hillside
西面之天然山坡



A closer view of Western Natural Hillside

西面天然山坡的近望



Boulder 2 (Before Stabilization Works)

大石二〔加固工程前〕



Boulder 2 - Stabilization Works in Progress (Formwork Erected)

在大石二之模板建造



Boulder 3 - Stabilization Works in Progress (Formwork Erected)

在大石三之模板建造



Concrete Buttress (Example at Discovery Bay)

混凝土扶壁以加固大石 (例:愉景灣)



Small Boulders on man-made slopes

在人造斜坡上的散石